



مجلس مراجعة قواعد التوزيع
DISTRIBUTION CODE REVIEW PANEL

Notice-3 to Suppliers/Agents/Manufacturers

Base on the encountered failures on Feeder Pillars (catching fire) DCRP requests all approved feeder pillars & cutout box manufacturers to submit the full type test report as per IEC 61439 Part1 & Part2 including **Temperature Rise Test**.

In case if the type test has not been conducted as per IEC at earlier times, then companies should arrange to conduct the test on a reputed third party laboratory (European Only) in the presence of DCRP officials.

Deadline for submitting the above full type test requirements will be **30th September 2010**. Afterwards any company not conducted the required type test will be considered not meeting DCRP approval requirements & will be exposed to suspension at any time without any prior notification.

Regards



Chairman
Distribution Code Review Panel



Date: 14/10/2009

P.O Box, 1239 / P.C, 131 Hamryah, Sultanate of Oman
Telephone : 24588600 / 24588691 - Fax, 24523656
E-mail : dcrp@medcoman.com

ص.ب- ١٢٣٩ - الرمز البريدي ١٦١ العمرية - سلطنة عمان
هاتف: ٢٤٥٢٣٦٥٦ / ٢٤٥٨٨٦٩١ فاكس
البريد الإلكتروني: dcrp@medcoman.com